




KHAITAN INDUSTRIAL
EXPECT THE BEST

**KI C4SA HD
MARBLE CUTTER**

MARBLE CUTTER EXPLODED VIEW





SPARE PARTS LIST

No.	Description	QTY	No.	Description	QTY
1	Screw M4x12	1	27	Washer 8x18x1.2	1
2	Gear box cover front	1	28	Bearing 608	1
3	Bolt M7x16	1	29	ST Screw M5x60	2
4	Outer flange	1	30	Stator	1
5	Inner flange	1	31	Tension spring	2
6	Hex Screw M5*20	1	32	Housing	1
7	Gear Box Cover	2	33	ST Screw M5x45	3
8	Output shaft	1	34	Carbon brush holder	2
9	Front cover	1	35	Carbon brush	2
10	Bearing 6201	1	36	Carbon brush cover	2
11	Circlip $\Phi 32$	1	37	Dust proof cover	1
12	Steel $\emptyset 12 \times \emptyset 18 \times 5.4$	1	38	ST Screw 4.2x13	2
13	KEY 3x3.7x $\emptyset 10$	1	39	Cable	1
14	Gear	1	40	Cable sleeve	1
15	Circlip for shaft $\Phi 12$	1	41	ST Screw 4.2x22	2
16	Bearing 626	2	42	ST Screw 4.2x16	5
17	Gear box	1	43	Right handle	1
18	Depth adjust lever	1	44	Cable clip	2
19	Circlip for shaft $\Phi 14$	1	45	Switch	1
20	Bolt M8x16	1	46	Switch cover	1
21	O Ring $\emptyset 26 \times \emptyset 2$	1	47	Left handle	1
22	Pinion	1	48	Switch self-lock cap	1
23	KEY 2.5	1	49	Base plate	1
24	Bearing 629	1	50	Hex nut M5	1
25	Washer 9x22x1.2	1	51	Bolt M5x35	1
26	Armature	1			